

DATE 17 MAY 61 0130Z

SECRET

TO : DIRECTOR 25X1A

FROM : [REDACTED]

ACTION: DPD (1,2,3,4,5,6,7,8,9,10)

INFO : S/C (11)

JAD

25X1A

ROUTINE

IN 08113

TOR: 17 MAY 61 0201Z

TO [REDACTED] 25X1A

INFO

DATE

1645

TACKLE [REDACTED] 25X1A

25X1A

REF: [REDACTED] 0301 (OUT 0816)

1. MISSION HT-61-91 WITH SYSTEMS THREE AND SIX
CONDUCTED 16 MAY WITH FOLLOWING RESULTS:

A. ALTERNATOR FAILED 18 MINUTES AFTER POWER APPLIED
TO SYSTEMS.

B. SYSTEM THREE PREFLIGHT AND POST FLIGHT GOOD.
NO INTERCEPTS PRIOR POWER FAILURE.

C. SYSTEM SIX PREFLIGHT AND POST FLIGHT GOOD.
FOLLOWI INTERCEPTS NOTED PRIOR POWER FAILURE:



25X1D

2. IT IS QUITE EVIDENT PRESENT POWER SOURCE FOR [REDACTED]
SYSTEMS NOT OPERATIONAL RELIABLE. THIS WILL BE SUBJECT
SUBSEQUENT CABLES.

25X1D

SECRET

END OF MESSAGE